

1.



2x M1.4x10mm FHCS

2.




1/10 WARN 9.5CTI WINCH






3.



M3x4mm Socket Set Screws

4.




1/10 WARN 9.5CTI WINCH






5. Insert the wires into the case.



6. Solder wires onto motor




1/10 WARN 9.5CTI WINCH






7.



4x M2x5mm SHCS

8.




1/10 WARN 9.5CTI WINCH






9.



10.



1/10 WARN 9.5CTI WINCH



